H&M INTERNATIONAL TRANSPORTATION, INC.

February 17, 2012

FILED
JACKSONVILLE, FLORIDA
FEB 22 2012
CLERK, U.S. BANKRUPTCY COURT
MIDDLE DISTRICT OF FLORIDA

United States Bankruptcy Court
Middle District OF Florida
300 North Hogan Street Suite 3-305
Jacksonville, Florida 32202

In re: Trailer Bridge Inc (Debtor)

Case No: 3:11-bk-08348-JAF

Debtor's Objection to Certain Amended and Superseded and Duplicate Claims

H & M International Transportation Inc. (Claimant)

We herewith dispute the Debtors objection to the referenced case on the bases that we provided trucking services for the Debtor as per the attached documentation.

Authorized by:

George Willmott
Treasurer
H & M International Transportation Inc.
485B Route One South
Iselin New Jersey 08830
T 732-510-4656
F 732-510-4693
gwillmott@hmit.net

H & M INTERNATIONAL TRANSPORTATION, INC.

'EVERY STEP OF THE WAY'

Invoice

Invoice#: 3580000532

Invoice Date: 12/11/2008

Bill To: TRAILER BRIDGE
10405 NEW BERLIN RD.
JACKSONVILLE FL 32226
Att: PAM JANTZEN

Account#: 47562
Service Date: 12/01/2008
Reference: TIRE REPAIRS

Shipper:

Consignee:

Description	Unit	Qty	Rate	Extension
REPAIRS DONE ON TRLZ 201054 11/26/08	EA	1	44.53	44.53

COMMENTS:
TRLZ 201054 REF# 132135
SEE ATTACHED BACK UPS----------

TERMS: NET UPON PRESENTATION

Please Pay This Amount: $44.53

Please make all checks payable to:
H&M International Transportation, Inc.
P.O. Box 822093
Philadelphia, PA 19182-2093

H&M International Transportation, Inc.
732-510-4640

H & M INTERNATIONAL TRANSPORTATION, INC.

'EVERY STEP OF THE WAY'

Invoice

Invoice#: 3580001939

Invoice Date: 11/04/2011

Bill To: TRAILER BRIDGE
10405 NEW BERLIN RD.

JACKSONVILLE FL 32226
Att: PAM JANTZEN

Account#: 47562
Service Date: 10/31/2011
Reference: REPAIRS

Shipper:

Consignee:

Description	Unit	Qty	Rate	Extension
REPAIRS ON TRBZ100803, REF 199559	EA	1	32.00	32.00
REPAIRS ON TRBZ520404, REF 207395	EA	1	151.75	151.75
REPAIRS ON TRBZ101701, PO# JJ102511J	EA	1	1,149.66	1,149.66
REPAIRS ON TRBZ100506, REF 199581	EA	1	191.61	191.61

COMMENTS:
SEE ATTACHED BACKUPS----------

TERMS: NET UPON PRESENTATION

Please Pay This Amount: $1,525.02

Please make all checks payable to:
H&M International Transportation, Inc.
P.O. Box 822093
Philadelphia, PA 19182-2093

H&M International Transportation, Inc.
732-510-4640

Owners PO# TRBZ 100803

H & M International Tire Workorder

Workorder # 199559

Damage PO #

Unit Number:	TRBZ 100803
Vin#:	3H3C5925 2WT005753
Make:	Hunnavd
Associated Unit #:	TRBR-231983

Year:	1998
License #:	TCMW T729903
Load / Empty	Empty X
Mechanic Name:	Nigre
Railyard:	BRP
Yard Location:	
Slot Number:	Shop
Date:	10-24-11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	03	14	RIF	LIR		PLAT Repair						29.00	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
				1 patch			3.00

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name: Rush.
Trk Number: CI 10020
Driver's Signature: [illegible]
Date: 10-25-11 Time:

Total Labor Hrs.	$
Total Labor Cost	$ 29.00
Total Parts Cost	$ 3.00
Tax	$
Total Invoice Cost	$ 32.00

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Workorder # 207395

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number:	TRBZ520404
Vin#:	5B7021278
Make:	STRick
Associated Unit #:	TRBU465139

Year:	5-95
License #:	7316290
Load / Empty	Empty X
Mechanic Name:	30E V
Railyard:	Bed Ford Pk
Yard Location:	Shop
Slot Number:	
Date:	10-24-11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	01	16	ROR	1020								29.00	107.15

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
1509	01	14	RR	1 TUBE			15.60

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name: Trailer Bridge INC
Trk Number: 651
Driver's Signature: Robert [illegible]
Date: 10-24-11 Time: 6:20 PM

Total Labor Hrs.	$
Total Labor Cost	$ 29.00
Total Parts Cost	122.75
Tax	$
Total Invoice Cost	151.75

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Trailer Bridge

Owners PO# II 102511-J

H & M International Tire Workorder

Workorder # 207332

Damage PO #

Unit Number:	TRBZ 101701
Vin#:	3H3C5BZS8WT063442
Make:	HYUNDAI
Associated Unit #:	TRBG-232575

Year:	10-98
License #:	T270456
Load / Empty	X
Mechanic Name:	
Railyard:	CSX B P
Yard Location:	SHOP
Slot Number:	
Date:	10 25 11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1115	03	34	LIF	295/75 R22.5	GENERAL	A33T-4407	—	GS	DA3T-2308	RFG 3811		29—	162.61
1115	03	34	LOF		BS	32BT-0708	—	BS	2GBT-2703	RFG 3811		29—	162.61
1115	03	34	LIR		FT	W1BT-4208	—	GS	MJ3T-1805	RFG 4211		29—	162.61
1115	03	34	LOR		GENERAL	A33T-0308	—	HINKOOK	BJ02-3240	RFG 4211		29—	162.61
1115	03	34	RIF		FT	W1BT-1261	—	BS	EP3T-079	RFG 4211		29—	162.61
1115	03	14	ROF		BS	EP6N-8301	—	DT	8F-3805	RFG 4211		29—	162.61
				LP									

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name:	X Trailer Bridge III
Trk Number:	X 651
Driver's Signature:	X
Date:	X 10-25-11
Time:	

Total Labor Hrs.	$
Total Labor Cost	$ 174—
Total Parts Cost	$ 975.66
Tax	$ —
Total Invoice Cost	$ 1149.66

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Trailer Bridge

Owners PO#

H & M International Tire Workorder

Workorder # 199581

Damage PO #

Unit Number: TRBZ 100506	Year: 1997
Vin#: VT00296	License #: T786270
Make: HYUNDAI	Load Empty X
Associated Unit #: TRBU 231128	Mechanic Name: Sonny

Railyard: Bedford PK	
Yard Location: Shop	
Slot Number:	
Date: 10-28-11	

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1115	03	34	RIR	295/75R22.5 LP	General	A3371W61508	RPSE2109	MAXSTEEL	DA37DBA237	RPT4211		29—	162.61

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name: Trailer Bridge INC
Trk Number: 651
Driver's Signature:
Date: 10-25-11 Time: 15:00

Total Labor Hrs.	$
Total Labor Cost	$29—
Total Parts Cost	$162.61
Tax	$—
Total Invoice Cost	$191.61

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

H & M INTERNATIONAL TRANSPORTATION, INC.

'EVERY STEP OF THE WAY'

Invoice

Invoice#: 3580001915

Invoice Date: 10/18/2011

Bill To: TRAILER BRIDGE
10405 NEW BERLIN RD.

JACKSONVILLE FL 32226
Att: TODD SUNDESTEN

Account#: 47562
Service Date: 10/14/2011
Reference: REPAIRS

Shipper:

Consignee:

Description	Unit	Qty	Rate	Extension
REPAIRS ON TRBZ432774, REF 199641	EA	1	42.50	42.50
REPAIRS ON TRBZ100733, REF 199447	EA	1	191.61	191.61
REPAIRS ON TRBZ360727, REF 199344	EA	1	253.50	253.50

COMMENTS:
SEE ATTACHED BACKUPS----------

TERMS: NET UPON PRESENTATION

Please Pay This Amount: $487.61

Please make all checks payable to:

H&M International Transportation, Inc.
P.O. Box 822093
Philadelphia, PA 19182-2093

H&M International Transportation, Inc.
732-510-4640

Workorder # 199641

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number:	TRBU 4327774
Vin#:	UMC 1015516
Make:	
Associated Unit #:	TRBU 413899

Year:	9-05
License #:	2530868
Load	Empty X
Mechanic Name:	Joe V
Railyard:	Bedford Pk
Yard Location:	Shop
Slot Number:	
Date:	10-13-11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	01	16	LOR	1020								29—	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
1509	01	14	LR	1 Tube			13.50

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name:
Trk Number:
Driver's Signature: Juan Lee Rush
Date: Time: 4-Bo 6.40

Total Labor Hrs.	$
Total Labor Cost	$29—
Total Parts Cost	$13.50
Tax	$ —
Total Invoice Cost	$42.50

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Trailer Bridge

Workorder # 199447

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number:	TRBZ 100733
Vin#:	VT004263
Make:	HYUNDAI
Associated Unit #:	TRBU 230202

Year:	12-97
License #:	7203973
Load	Empty X
Mechanic Name:	JOE V

Railyard:	Bedford Pk
Yard Location:	shop
Slot Number:	
Date:	10-12-11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1115	03	13	ROR	275R22.5	Michelin	BLES BN1X4503	RESE2107	Bridgestone	2CBT3H6J1506	RXD35708		25	162.61

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name:	Rush Transport
Trk Number:	
Driver's Signature:	Francisco Herrera
Date:	10-12-11
Time:	16:30

Total Labor Hrs.	$
Total Labor Cost	$ 25
Total Parts Cost	$ 162.61
Tax	$ —
Total Invoice Cost	$ 191.61

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Trailer Bridge

H & M International Tire Workorder

Owners PO#

Workorder # 199344

Damage PO #

Unit Number:	TBBZ-360727
Vin#:	L81CG5327TT104905
Make:	SINGAMAS
Associated Unit #:	TBBG-260053

Year:	07-2007	Railyard:	CSX B P
License #:	1982307	Yard Location:	
Load	Empty X	Slot Number:	Shop
Mechanic Name:	Glas	Date:	10 14 11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1115	03	9	LIR	11225	L LONG	0409T-1607	=	B S	EH3T-1309	RF43611		29—	97.75
1115	03	14	LOR	11225	L LONG	0409T-1607	=	M S	0425-4604	RF43611		29—	97.75

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name: X DONNELLY
Trk Number: X 408
Driver's Signature: X mah
Date: X 10.14.11 Time:

Total Labor Hrs.	$
Total Labor Cost	$ 58—
Total Parts Cost	$ 195.50
Tax	$ —
Total Invoice Cost	$ 253.50

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

H & M INTERNATIONAL TRANSPORTATION, INC.

'EVERY STEP OF THE WAY'

Invoice

Invoice#: 3580001921

Invoice Date: 10/28/2011

Bill To: TRAILER BRIDGE
10405 NEW BERLIN RD.

JACKSONVILLE FL 32226
Att: TODD SUNDESTEN

Account#: 47562
Service Date: 10/21/2011
Reference: REPAIRS

Shipper:

Consignee:

Description	Unit	Qty	Rate	Extension
REPAIRS ON TRBZ100506, REF 199783	EA	1	64.00	64.00
REPAIRS ON TRBZ101986, REF 207254	EA	1	32.00	32.00

COMMENTS:
SEE ATTACHED BACKUPS----------

TERMS: NET UPON PRESENTATION

Please Pay This Amount: $96.00

Please make all checks payable to:

H&M International Transportation, Inc.
P.O. Box 822093
Philadelphia, PA 19182-2093

H&M International Transportation, Inc.
732-510-4640

Owners PO#

H & M International Tire Workorder

Workorder # 199783

Damage PO #

Unit Number: TRBZ 100506	
Vin#: 3H3G54252V T002916	
Make: HYUNDAI	
Associated Unit #: TRBG -230686	

Year: 11-97	Railyard: CSX B P
License #: T786270	Yard Location:
Load Empty X	Slot Number: SHOP
Mechanic Name: Chas	Date: 10/18/11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	07	16	ROR	11R22.5	1	FLAT						29.00	
1100	07	16	LIR	11R22.5	1	FLAT						29.00	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
				2 patch			6.00

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name: X Trailer Bridge
Trk Number: X 651
Driver's Signature: X
Date: X 10-18-11 Time:

Total Labor Hrs.	$
Total Labor Cost	$ 58.00
Total Parts Cost	$ 6.00
Tax	$ ~~6.00~~
Total Invoice Cost	$ 64.00

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Trailer Bridge

H & M International Tire Workorder

Owners PO#

Workorder # 207254

Damage PO #

Unit Number:	TRBZ-101986
Vin#:	3H3C5[illegible]3258X T029891
Make:	HYUNDAI
Associated Unit #:	TRBU-232195

Year:	7-99	Railyard:	CSX BP
License #:	T291823	Yard Location:	
Load	Empty X	Slot Number:	SHOP
Mechanic Name:	Elias	Date:	10-21-11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	OB	16	R/F	11R22.5	1	PATCH						29—	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
				PATCH			3—

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name:	X DANNELEY - TRANSRAIL
Trk Number:	X 408
Driver's Signature:	X [illegible]
Date:	X 10-21-2011 Time:

Total Labor Hrs.	$
Total Labor Cost	$29—
Total Parts Cost	$ 3—
Tax	$ —
Total Invoice Cost	$32—

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

H & M INTERNATIONAL TRANSPORTATION, INC.

'EVERY STEP OF THE WAY'

Invoice

Invoice#: 3580001905

Invoice Date: 10/13/2011

Bill To: TRAILER BRIDGE
10405 NEW BERLIN RD.

JACKSONVILLE FL 32226
Att: TODD SUNDESTEN

Account#: 47562
Service Date: 10/07/2011
Reference: REPAIRS

Shipper:

Consignee:

Description	Unit	Qty	Rate	Extension
REPAIRS ON TRBZ360345, REF 198897	EA	1	29.00	29.00
REPAIRS ON TRBZ100463, REF 199038	EA	1	223.61	223.61
REPAIRS ON TRBZ431254, REF 199042	EA	1	149.65	149.65
REPAIRS ON TRBZ100506, REF 198894	EA	1	32.00	32.00

COMMENTS:
SEE ATTACHED BACKUPS----------

TERMS: NET UPON PRESENTATION

Please Pay This Amount: $434.26

Please make all checks payable to:

H&M International Transportation, Inc.
P.O. Box 822093
Philadelphia, PA 19182-2093

H&M International Transportation, Inc.
732-510-4640

Workorder # 198897

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number:	TRBZ 360345
Vin#:	77104521
Make:	SINGAMAS
Associated Unit #:	TRBU 231737

Year:	4-07
License #:	1930035
Load	Empty X
Mechanic Name:	JOE V
Railyard:	BedFordPk
Yard Location:	Shop
Slot Number:	
Date:	10-4-11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	1	16	ROF	10225								29.00	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name:	BRIGHTWAY
Trk Number:	584
Driver's Signature:	[signature]
Date:	Time: 1740

Total Labor Hrs.	$
Total Labor Cost	$ 29.00
Total Parts Cost	$ —
Tax	$
Total Invoice Cost	$ 29.00

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Trailer Bridge

Workorder # 199038

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number: TRBZ-100463	Year: 11-97
Vin#: 3H3C542SXVT002873	License #: T156093
Make: HYGNDAI	Load Empty X
Associated Unit #: TRBY-268769	Mechanic Name: [illegible]

Railyard: CSX BP	
Yard Location: SHOP	
Slot Number:	
Date: 10-3-11	

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1115	03	14	LOF	11R22.5	GENERAL	A33T-3406	—	BS	EP3T-1608	RFG 3911		29—	162.61
1100	T	16	LOR	11R22.5	1	FLAT	—	—	—	—		29—	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
			LOR	PATCH			3—

Condition Code
01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair	1278-clamp	1208-Rim
1115-Tire	1260-Stud and Nut	Tube Type
1509-Tube	1266-Spacer	
1230-Flap	1207-Rim Tubeless	

Why Made Codes

01-Associated Repair	09-Slick Tread	14-Cut/Torn	34-Skid Flat
02-Bent	10-Seperated Cap	15-Worn Out	
03-Broken	11-Blister/Knots	16-Flat Tire	
08-Missing	13-Run Flat	17-Weather Check/Channel Cracking	

Cartage Co. Name: X Donnelly
Trk Number: X 487
Driver's Signature: X O Z Zambrano
Date: X 11/3/11 Time:

Total Labor Hrs.	$
Total Labor Cost	$58—
Total Parts Cost	$165.61
Tax	$ —
Total Invoice Cost	$223.61

Location Codes

LOF-Left Outside Front	LIR-Left Inside Rear	RIF-Right Inside Front
LIF-Left Inside Front	ROF-Right Outside Front	ROR-Right Outside Rear
LOR-Left Outside Rear		RIR-Right Inside Rear

Trailer Bridge

Workorder # 199042

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number:	TRBZ 431254
Vin#:	LJRG412 6951013638
Make:	CIMC
Associated Unit #:	—

Year:	08-05
License #:	2527044
Load	Empty X
Mechanic Name:	Chas
Railyard:	CSX B P
Yard Location:	
Slot Number:	SHOP
Date:	10 3 11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1115	03	34	ROR	18 20	LEOPARD	8D25-4705	—	KSRJ	9S 430T	RPAy 3911		29—	107.15

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
				TUBE			13.50

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name: X TRAILER BRIDGE
Trk Number: X 6602
Driver's Signature: Scott Butler
Date: X 10-3-11 Time:

Total Labor Hrs.	$
Total Labor Cost	$29—
Total Parts Cost	$120.65
Tax	$ —
Total Invoice Cost	$149.65

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Workorder # 198894

Owners PO#

Damage PO #

H & M International Tire Workorder

Unit Number:	TRBZ100506
Vin#:	VT002916
Make:	HYUNDAI
Associated Unit #:	TRBU 232420

Year:	11-97
License #:	T786270
Load	Empty X
Mechanic Name:	JOE V
Railyard:	Bedford PK
Yard Location:	Shop
Slot Number:	
Date:	10-3-11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	B	16	ROR	225								29.00	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
			RR	Patch			3.00

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name: TRAILER BRIDGE
Trk Number: 662
Driver's Signature: Bart Butler
Date: 10-3-11 Time: 17:00

Total Labor Hrs.	$
Total Labor Cost	$ 29.00
Total Parts Cost	$ 3.00
Tax	$
Total Invoice Cost	$ 32.00

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

H & M INTERNATIONAL TRANSPORTATION, INC.

'EVERY STEP OF THE WAY'

Invoice

Invoice#: 3580001872

Invoice Date: 9/20/2011

Bill To: TRAILER BRIDGE
10405 NEW BERLIN RD.

JACKSONVILLE FL 32226
Att: TODD SUNDESTEN

Account#: 47562
Service Date: 09/16/2011
Reference: REPAIRS

Shipper:

Consignee:

Description	Unit	Qty	Rate	Extension
REPAIRS ON TRBZ432774 ON 09/14/2011	EA	1	42.50	42.50

COMMENTS:
SEE ATTACHED BACKUPS----------
REPAIRS ON TRBZ432774, REF 196615

TERMS: NET UPON PRESENTATION

Please Pay This Amount: $42.50

Please make all checks payable to:
H&M International Transportation, Inc.
P.O. Box 822093
Philadelphia, PA 19182-2093

H&M International Transportation, Inc.
732-510-4640

Trailer Bridge

Workorder # 196615

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number:	TRBZ432774
Vin#:	1D15576
Make:	GMC
Associated Unit #:	TRAU 914035

Year:	4-05	Railyard:	Bedford Pk
License #:	253086B	Yard Location:	Shop
Load	Empty X	Slot Number:	
Mechanic Name:	JOEV	Date:	9-14-4

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	01	16	LIF	1020								29—	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
1509	01	14	LR	1 Tube			13.50

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name: TRAILER BRIDGE
Trk Number: 602
Driver's Signature: Brad Butler
Date: Time: 7:15pm

Total Labor Hrs.	$
Total Labor Cost	$29—
Total Parts Cost	$13.50
Tax	$—
Total Invoice Cost	$42.50

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

H & M INTERNATIONAL TRANSPORTATION, INC.

'EVERY STEP OF THE WAY'

Invoice

Invoice#: 3580001894

Invoice Date: 10/05/2011

Bill To: TRAILER BRIDGE
10405 NEW BERLIN RD.

JACKSONVILLE FL 32226
Att: TODD SUNDESTEN

Account#: 47562
Service Date: 09/30/2011
Reference: REPAIRS

Shipper:

Consignee:

Description	Unit	Qty	Rate	Extension
REPAIRS ON TRBZ419034 ON 09/26/2011	EA	1	85.00	85.00

COMMENTS:
SEE ATTACHED BACKUPS----------
REPAIRS ON TRBZ419034, REF 197134

TERMS: NET UPON PRESENTATION

Please Pay This Amount: $85.00

Please make all checks payable to:
H&M International Transportation, Inc.
P.O. Box 822093
Philadelphia, PA 19182-2093

H&M International Transportation, Inc.
732-510-4640

Workorder # 197134

Owners PO#

Damage PO #

H & M International Tire Workorder

Unit Number: TRB2419034	
Vin#: 1ABCG40244H006338	
Make: AT	
Associated Unit #: TRBU459496-8	

Year: 2000	Railyard: BFP
License #: 530434	Yard Location: SHOP
Load Empty ✓	Slot Number:
Mechanic Name: AS	Date: 9-26-11

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1509	01	16	RIF	1020								29.00	
1509	01	16	ROF	1020								29.00	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
1509	01	14	RFlat	2TU38			27.00

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name:	US-1
Trk Number:	31-154
Driver's Signature:	Stanley h
Date:	Time: 2200

Total Labor Hrs.	$
Total Labor Cost	$ 58.00
Total Parts Cost	$ 27.00
Tax	$
Total Invoice Cost	$ 85.00

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

H & M INTERNATIONAL TRANSPORTATION, INC.

'EVERY STEP OF THE WAY'

Invoice

Invoice#: 3580001975

Invoice Date: 12/06/2011

Bill To: TRAILER BRIDGE
10405 NEW BERLIN RD.

JACKSONVILLE FL 32226
Att: TODD SUNDESTEN

Account#: 47562
Service Date: 11/30/2011
Reference: REPAIRS

Shipper:

Consignee:

Description	Unit	Qty	Rate	Extension
REPAIRS ON TRBZ360830, REF 201302	EA	1	280.88	280.88
REPAIRS ON TRBZ101944, REF 201545	EA	1	32.00	32.00

COMMENTS:
SEE ATTACHED BACKUPS----------

TERMS: NET UPON PRESENTATION

Please Pay This Amount: $312.88

Please make all checks payable to:

H&M International Transportation, Inc.
P.O. Box 822093
Philadelphia, PA 19182-2093

H&M International Transportation, Inc.
732-510-4640

Workorder # 201302

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number: TRBZ 360830	Year: 2007
VIN: [illegible]	License #: [illegible]
Make: Strgamas	Load Empty ✓
Associated Unit #: TRBU 230581	Mechanic Name: [illegible]

Railyard: BP	
Yard Location: [illegible]	
Slot Number: Shop	
Date: 11-18-11	

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1115	03	17	LOR	11R25	Cheo	8D25 8201		Dynastor	9525 199	RFT 441		29—	111.44
1115	03	14	LIR	11R25	Cheo	8D25 0201		MABSK	04 9TETS	RFT 441		29—	111.44
				11X									

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim Tube Type

Cartage Co. Name: ✓
Trk Number: ✓ 2020
Driver's Signature: Ali sherife
Date: Time:

Total Labor Hrs.	$
Total Labor Cost	$58—
Total Parts Cost	$222.88
Tax	$—
Total Invoice Cost	$280.88

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear

Workorder # 201545

Owners PO#

H & M International Tire Workorder

Damage PO #

Unit Number: TRBZ 101944	Year: 799
VIN:	License #:
Make: HYUNDAI	Load Empty X
Associated Unit #: TRBL 231415	Mechanic Name: Joey

Railyard: Bedford Park	Yard Location:
Slot Number:	
Date: 11-29-11	

Job Code	CC	Why Made	Location	Tire Size	Brand Off	DOT Off	Recap Off	Brand On	DOT On	Recap On	Labor Hrs.	Labor Cost	Part Cost
1100	B	16	LIR	295/75R22.5								29.00	

Job Code	CC	Why Made	Loc.	Description of Parts	Labor Hrs.	Labor Cost	Part Cost
	01	14	LR	1 Patch			3.00

Condition Code

01-New
02-Used
03-Recap
06-Material
07-Labor
A-Secure
B-Patch

Job Codes

1100-Flat Repair
1115-Tire
1509-Tube
1230-Flap
1278-clamp
1260-Stud and Nut
1266-Spacer
1207-Rim Tubeless
1208-Rim
Tube Type

Why Made Codes

01-Associated Repair
02-Bent
03-Broken
08-Missing
09-Slick Tread
10-Seperated Cap
11-Blister/Knots
13-Run Flat
14-Cut/Torn
15-Worn Out
16-Flat Tire
17-Weather Check/Channel Cracking
34-Skid Flat

Cartage Co. Name:	DONNELLY
Trk Number:	468
Driver's Signature:	11-29-11
Date:	Time: 17:10

Total Labor Hrs.	$
Total Labor Cost	$29.00
Total Parts Cost	$ 3.00
Tax	$
Total Invoice Cost	$32.00

Location Codes

LOF-Left Outside Front
LIF-Left Inside Front
LOR-Left Outside Rear
LIR-Left Inside Rear
ROF-Right Outside Front
RIF-Right Inside Front
ROR-Right Outside Rear
RIR-Right Inside Rear